

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5(a)

ACCESS PATH SETTINGS INFORMATION IN
THE SAN INTEGRATED MANAGEMENT MECHANISM

ACCESS PATH	HOST	HBA(WWN,PID)	STORAGE DEVICE	FCA (WWN,PID)	REGION
600	110	111 (WWNa, PIDa)	410	411 (WWNc, PIDc)	415
601	120	121 (WWNa, PIDa)	410	412 (WWNd, PIDd)	416

FIG. 5(b)

STORAGE AFFINITY TABLE (FOR HOST 110)

HBA	ACCESS DESTINATION FCA INFORMATION	FCA SUBORDINATE ACCESS REGIONS
111	WWNc	415
112	NONE	NONE

FIG. 5(c)

SWITCH ZONING TABLE (FOR SWITCH 300)

ZONE NAME	ZONING SETTINGS
A	WWN a, WWN c
B	WWN e, WWN d

FIG. 5(d)

HOST AFFINITY TABLE (FOR STORAGE 410)

FCA	ACCESSIBLE HBA INFORMATION	CORRESPONDING REGION
411	WWN a	415
412	WWN e	416


FIG. 6

FIG. 7




FIG. 8




FIG. 9

PROBLEM INFORMATION RECEIVED	PROBLEM REPORT CONTENT
FCA ERROR + SWITCH PORT ERROR + HOST-SIDE ACCESS ERROR, SWITCH PORT ERROR + HOST-SIDE ACCESS ERROR	FCA ERROR SWITCH PORT ERROR

FIG.10

